

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**




FIG. 1A




FIG. 1B




FIG. 1C




FIG. 1D




FIG. 2A




FIG. 2E




FIG. 2B



FIG. 2D




FIG. 2C




FIG. 3A



FIG. 3B




FIG. 3C




FIG. 3D



FIG. 3E




FIG. 4A



FIG. 4B




FIG. 4C




FIG. 4D




Figure 5







FIG. 6A.






Shaft tapered toward the end of the grip




Side view



Cross section

Figure 8A



1 3/4" diameter




Figure 8B




Figure 8C

Grip placed on shaft




Figure 9A




Figure 9B




Figure 10